Attending: Guests:
C. Loveland B. Homa M. Heide
R. Boyer C. Kratochvil N. Haight

D. Griffith M. Schroedel J. Davis

Chairman of the Board Loveland called the Special Meeting to order at 6:30 pm. The public was notified via front signage, district website, and Town of Union website.

Motion was made by Schroedel, second by Davis to enter into executive session at 6:31 pm for personnel matter

Return to regular session at 6:49 pm

The result was ongoing communications.

Motion was made by Loveland, second by Schroedel to adjourn the meeting at 6:49 pm. All Commissioners voted in favor and the motion passed unanimously.

Respectfully submitted,

### Betty J Homa

Betty J. Homa District Secretary



230 INDUSTRIAL PARK ROAD, P.O. BOX 90, MEYERSDALE, PA 15552 ~ PHONE 814-634-8373 - FAX 814-634-0076

January 19, 2021

West Corners Fire District 500 Day Hollow Road Endicott, NY 13760

Dear Sir:

Following find quote on additions and deletions to your new pumper per your review meeting with Pete Amos on 12/30/20.

#### Chassis Questions:

What is the warranty on the cab's rubber underbody coating? Two years

Is the auxiliary power under the officer's seat storage compartment or behind it? It is actually in the storage compartment. The wording reads "installed in the officer side under-seat storage compartment."

Is the engine brake a Jacobs engine brake? Yes

What is the brand of air valve is being used for the pump shift? Williams control.

What is the cost to upgrade to 33,000 GVW for the rear? Cost: \$1,694.00 Xyes no

Does the air inlet have an inline check valve? Yes

Are the heater hoses silicon with stainless clamps? Yes

How wide is the front opening of the forward facing under seat box in the rear of the cab? They want to maximize the opening, 8.63" x 32"

Can we add a 110 outlet to the officer side MDT area on the officer's switch panel? This can be discussed at prepaint.

Is there an option for low 12-volt battery disconnect that would allow starting not charging when battery gets too low as a solution to members forgetting to plug the truck in at the station? Jumper Posts

Is the 360" view HD camera system a recordable system that could also be used as a dash camera? Are the files easily readable? No You would need to order part number 5622-026 and 5706-035 to achieve this.

Cost: \$1,984.00 \_\_\_\_yes \_X\_no

What is the size of the exhaust tube exiting the truck? The pipe is 5" but with the cooling tube on the end it goes to 7"

What is the location of the hour meter? Lower left dash.

No lights of any kind on the front bumper.



Delete two-tone cab paint. Cab to be one color, red to match ladder truck we built for them.

### Changes to specifications requested:

Credit \$1,322.00 <u>X</u> yesno
Tire rims to be painted black IPO lower body color.  Cost: \$428.00 _X yesno
Remove front supplemental brake and replace with 2 <sup>nd</sup> air brake control on the officer's side or middle of dog house protected with guard to prevent accidental engagement.  Cost: \$334.00 <u>X</u> yesno
Remove foot switches for Q2B siren – activation should be by a single combo switch up for siren and down fo brake.
Flip the position of the air horns and sirens in the front bumper to match the picture. Air horns on outside and sirens inside similar to the ladder we built.
Delete Air horn/Elec horn selector switch (#5504-002) Credit: \$41.00 vesno
Delete head light flasher & switch (#5409-002, #5425-018). Credit: \$74.00 <u>✓</u> yesno
Delete SCBA mask pouches (#1209-002, #1212-002). Credit: \$124.00no
Switch mirrors to remote and heated convex mirrors as well as main mirrors (#1504-154).  Cost: \$176.00 _X_yesno
Move electrical inlet to step well area (#5209-021) and change to a non-auto eject cutlet (#5204-006). Credit: \$212.00 ★ yesno
Delete clock (#5612-007). Credit: \$119.00yesno
Switch Panel layout to be as similar to the present ladder truck as possible. Picture to follow.
Body Change Requested: Striping on truck to be black reflective IPO white reflective. This can be discussed at prepaint.
Please indicate which items you wish to add or delete and sign and return one copy
Sincerely, Accepted: Met July
Mark R. Albright President & CEO Date: 1-22-3/



### www.4guysfire.com

230 INDUSTRIAL PARK ROAD, P.O. BOX 90, MEYERSDALE, PA 15552 ~ PHONE 814-634-8373 ~ FAX 814-634-0076

February 22, 2022

West Corners Fire District
500 Day Hollow Road
Endicott, NY 13760

Dear Sir:

Following find quote on changes to your new pumper per your request.

Add a Whelen Arrow stick to the rear of the body. The arrow stick will be recess mounted below the rear scene links.

Please indicate which items you wish to add or delete and sign and return one copy

Sincerely,

Accepted:

Mark R. Albright President & CEO

Cost \$2,826.00 / yes \_\_\_no

Date: 2-23-22